

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:							
Company	Mike Davis						
OGM	Karl Houskeeper						

Inspection Report

Permit Number:	C0410002			
Inspection Type:	COMPLETE			
Inspection Date:	Tuesday, March 01, 2011			
Start Date/Time:	3/1/2011 8:00:00 AM			
End Date/Time:	3/1/2011 2:30:00 PM			
Last Inspection:	Tuesday, February 08, 2011			

Inspector: Karl Houskeeper,
Weather: Clear, Temp. 19 Deg. F.
InspectionID Report Number: 2666

Accepted by: jhelfric 3/8/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: SUFCO MINE

Address: 597 SOUTH SR24, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	720.48
Total Disturbed	48.43
Phase I	
Phase II	
Phase III	

Mineral Ownership

✓ Federal

State
County

Fee Other

Types of Operations

✓ Underground☐ Surface

□ Loadout□ Processing

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

RECEIVED MAR 3 0 2011

DIV. OF OIL, GAS & MINING

Inspector's Signature:

Kall. Houseyer

Date

Tuesday, Marc 11

OIL CAS & MINING

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0410002 Inspection Type: COMPLETE

Inspection Date: Tuesday, March 01, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	•		✓	-
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		•	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	~			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.	Roads: Construction, Maintenance, Surfacing	✓			
16.t	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	V			
21.	Bonding and Insurance	/			
22.	Other	V			

Permit Number: C0410002 Inspection Type: COMPLETE

Inspection Date: Tuesday, March 01, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/041/0002 was issued effective 05/21/2007 and expires 05/21/2012.

- -Certificate of Insurance policy number GL093-61-11, issued 07/31/2010 and terminates 07/31/2011.
- -UPDES permit # UT0022918 effective 04/01/2006 and expires @ midnight 04/30/2011.
- -Air Quality permit DAQE-AN0665008-06, issued May 26, 2006.
- -SPCC Plan dated July 2004. The Plan is P.E. certified, stamped, signed and dated 09/10/2007 by a Utah P.E.

2. Signs and Markers

The ID signs located at the points of public access contained the necessary information.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Fourth quarter 2011 sediment pond inspection were done on: Mine site overflow pond, 10/20/2010, Waste Rock Pond 10/27/2010, and Mine site primary pond 11/1/2010.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for Decemberr 2010 and January 2011were reviewed. Outfall 001 did not discharge. Outfalls 002 and 003 discharged but did not exceed any parameters.

7. Coal Mine Waste, Refuse Piles, Impoundments

The Fourth quarter 2010 refuse pile inspection was done on 10//29/2010.